



Advanced Test Equipment Corp.

www.atecorp.com 800-404-ATEC (2832)

HPD II High Pressure Diffuser

Lasair® II 110 and Lasair III 110 Accessory



The HPD II reduces the pressure of dry, inert, non-toxic, non-flammable gases, such as Clean Dry Air (CDA), nitrogen, carbon dioxide and argon to a level acceptable for the Lasair II 110 and Lasair III 110 aerosol particle counters, which are designed to operate at atmospheric pressure.

BENEFITS

- Two models to reduce high-pressure gas between 40 – 100 psi or 75 - 150 psi to about atmospheric pressure
- Use in conjunction with a Lasair II-110 or Lasair III-110 particle counter to measure particles as small as 0.1 μm in CDA, nitrogen, carbon dioxide or argon
- Allows users to efficiently monitor pressurized gases with standard aerosol particle counters

FEATURES

- Specifically designed for use with the Lasair II-110 and Lasair III-110 particle counters
- Simple connections for gas inlet/outlet
- Filtration of any excess gas
- Particle counter can remain on, even when gas supply is off



**PARTICLE
MEASURING
SYSTEMS®**
a spectris company

Without measurement there is no control

HPD II High Pressure Diffuser

Lasair® II 110 and Lasair III 110 Accessory

Specifications

Particle size range	0.1 µm – 1.0 µm
Sample gas	Dry, inert, non-toxic, non-flammable gases (CDA, nitrogen, carbon dioxide, argon) NOTE: If using carbon dioxide, contact Particle Measuring Systems.
Sample gas pressure	Model HPD II 100: 40 - 100 psi Model HPD II 150: 75 - 150 psi
Sample gas flowrate	1 CFM
Sample gas temperature	50 – 90 °F (10 – 32 °C)
Inlet fitting	VCR-type, #4, 316-SS
Outlet fitting	3/8" ID with O-ring seal
Dimensions (h, w, d)	5.1 x 9.8 x 5.5 in (13 x 25 x 14 cm)
Weight	5.8 lb (2.6 kg)

Lasair® is a registered trademark of Particle Measuring Systems, Inc.
All trademarks are the property of their respective owners.
Particle Measuring Systems, Inc. reserves the right to change specifications without notice.
©2018 Particle Measuring Systems, Inc.
All rights reserved.



HEADQUARTERS

5475 Airport Blvd
Boulder, Colorado 80301 USA
T: +1 303 443 7100, +1 800 238 1801

Instrument Service & Support
T: +1 800 557 6363

Customer Response Center
T: +1 877 475 3317
E: info@pmeasuring.com

GLOBAL OFFICES

AUSTRIA
T: +43 512 390 500
E: pmsaustria@pmeasuring.com

BENELUX
T: +32 10 23 71 56
E: pmsbelgium@pmeasuring.com

BRAZIL
T: +55 11 5188 8227
E: pmsbrazil@pmeasuring.com

CHINA
T: +86 21 6113 3600
E: pmschina@pmeasuring.com

FRANCE
T: +33 (0)6 82 99 17 98
E: pmsfrance@pmeasuring.com

GERMANY
T: +49 6151 6671 632
E: pmsgermany@pmeasuring.com

ITALY
T: +39 06 9053 0130
E: pmsrl@pmeasuring.com

JAPAN
T: +81 3 5298 8175
E: pmsjapan@pmeasuring.com

KOREA
T: +82 31 286 5790
E: pmskorea@pmeasuring.com

MEXICO
T: +52 55 2271 5106
E: pmsmexico@pmeasuring.com

NORDIC
T: +45 707 028 55
E: pmsnordic@pmeasuring.com

PUERTO RICO
T: +1 787 718 9096
E: pmspuertorico@pmeasuring.com

SINGAPORE
T: +65 6496 0330
E: pmsingapore@pmeasuring.com

SWITZERLAND
T: +41 71 987 01 01
E: pmsswitzerland@pmeasuring.com

TAIWAN
T: 886-3-5525300 Ext: 301
E: pms taiwan@pmeasuring.com